


**Ricambi Auto Sport S. R. L**

 Av. San Martín 4235 - Caseros (1678)  
 Buenos Aires, Argentina Tel./ Fax: +54 011 46561818/8008

**NOVEDADES EN KITS DE DISTRIBUCION ENERO 2011**

Código	Aplicación	Tensores Incluidos	Correas	Referencia
KDT 104	Fiat Brava-Bravo-Marea-Palio-Siena 1.6 16V	1/2-050 1/2-028	158SHPN254H	SKF: <b>VKMA02242A</b>
KDT 106	Fiat Palio-Siena-Uno Motor Fire 1.4 (129 dientes)	1/2-056	129P8SD220H	SKF: <b>VKMA02206</b>
KDT 205	Renault Clio II 1.5 dCi	2/2-060	123SP270H	SKF: <b>VKMA06130A</b> DAYCO: KTB322 GATES: K015578XS INA: 530 0197 10
KDT 210	Renault Laguna II Phase 2 Berline, 1.8 i 16V 116cv Autom., 1.8 i 16V 118cv, 1.8 i 16V 118cv Autom., 1.8 i 16V 120cv, 1.8 i 16V 123cv Autom., 2.0 i 16V 135cv, 2.0 i 16V Turbo 165cv, 2.0 i 16V Turbo 165cv Autom., 2.0 i 16V Turbo 170cv Autom., 2.0 i 16V Turb	2/2-053 2/2-061	126SP270H	SKF: <b>VKMA06106</b>
KDT 301	Peugeot 205 1.4 Nafta (Motor TU3F 1992->)-206 1.6 Nafta (Motor TU5JP)-306 1.6 Nafta (Motor TU5JP) Citroën Saxo, Xsara, ZX 1.6 TU5JP	3/2-016	101SP170H	SKF: <b>VKMA03111A</b>
KDT 401	Ford Courier / Escort / Fiesta 1.8 D / 1.8 TD Desde 11/1995	4/2-011 4/2-025 4/2-037	116SHDN220H 085SHDN220H	SKF: <b>VKMA04106A</b>
KDT 402	Ford EcoSport-Nuevo Fiesta 1.4 TDCI - Citroën C3 1.4 TDCI	3/2-071 4/2-047	144SP+254H	SKF: <b>VKMA03140</b>
KDT 506	VW Fox 1.6 8v	5/2-036	135STP8M190H	