




NUEVOS PRODUCTOS 2012



Código	Aplicación	Nº Referencia	Foto
G5/2-044	Poly-V Polea Reparacion tensores 5/2-012 , 5/2-022 , 5/2-026 , 5/2-027 , 5/2-037 <i>Version Chapa embutida</i>	068145299R5 377260299 028260299.1	
G4/2-055	Distribución Fiesta/Focus/Mondeo 1.8 TD (66KW)	1215978 1113174 2T1Q6K254AA 1479084 XS4Q6B217AD 2T1Q6K254AB VKM 14108	
G2/2-070	Poly-V Laguna I 2.0 16V - Safrane II 2.0 16V / 2.5 20 V	7431 271 914 7431 275 380 534 0133 30 Gates:T38304	
G3/2-090	Distribución Peugeot 106 / 206 Motor 1.1 / 1.4 TU3JP / TU3A - 207 / Partner 1.4 8V TU3JP / TU3A - CITRÖEN Berlingo 1.4 desde motor 3666766 - C3 1.4 8V TU3P	0829.90 VKM 13253	
G5/2-048	Poly-V VW Amarok 2.0 Tdi, BiTdi	03G 145 276 VKM 31008	
G6/2-043	Poly-V DAEWOO: Evanda 1.4, 1.6 - Kalos 1.4, 1.5, 1.6, 1.8 - Lacetti 1.4, 1.6, 2.0, 1.8 - Nubira 1.4, 2.0, 1.6, 1.8, 1.5 - Orion 1.6, 1.8 - Rezzo 2.0 - Tacuma 1.8 CHEVROLET: Aveo 1.6, 1.4 - Blazer S10 4.3 - C1500 4.3 - C2500 2.0 - Epica 2.0 - Lova 1.5, 1.4, 1.6, 2.0 - Magnus 2.0 - Optra 1.6, 2.0 CHEVROLET : 10118713 - 96183113 - 25180907 - DAEWOO : 96183113 - KIA : 0K9A615993 GATES: T38024		
G13/2-005	Distribución Chrysler Neon 2.0 16V Sin Soporte	04884320AA GATES:T43001 F-551227	

NUEVOS PRODUCTOS 2012



Código	Aplicación	Nº Referencia	Foto
G16/2-009	Poly-V TOYOTA HILUX - LAND CRUISER 3.0D	166200L020	
G16/2-012	Poly-V HONDA New Civic desde (from) 2006	31170-RNA-A01 31170-RNA-A02 31170-RNA-A11 31170-RNA-G01 31170-RNA-G11 F-551449.01	
G16/2-013	Poly-V HONDA New Fit y City 1.5	31170-RBO-J01	
G4/2-058	Poly-V Transit 2.4 TDCi , 3.2 TDCi	6C1Q-6A228-BC 6C1Q- 6A228-BB 1385379 1445915 VKM 34702	
G21/2-021	Poly-V Camiones Volvo Motor D12 A / FH 12 1994 / 1998 Bus Volvo Motor D12 A / FH 12 1994 / 1998	3154315	
G21/2-031	Poly-V IVECO : Todas las versiones de Nuevo Stralis, Nuevo Trakker; Stralis, Trakker, Cavallino Attack, Cavallino y Eurocargo. Motores F3AE 0681, F2BE 0681/A/B/D, F3AE 0681/D/E	99471920 99436331 504046191 VKMCV 52003	
G21/2-032	Poly-V M.BENZ AXOR	4572003070 A4572003070	


NUEVOS PRODUCTOS 2012



Código	Aplicación	Nº Referencia	Foto
G21/2-033 Poly-V		4572001770 4572000070 A4572003470	
G3/2-088 Poly-V	307 / 807 Motor EW10A 2.0 16V 2.0 16V	C4 Motor EW10A 5751.C0 5751.G8 9663566180	
G1/2-059	Ducato 2.8 TD Maxi Cargo / Master 2.5 D y 2.8 dTi	7701044676 VKM 36017	
G2/2-071 Distribución	Logan / Sandero 1.6 8 V K7M desde 2010	8200908180	
G2/2-072 Poly-V	Megane 2 1.6 16V K4M (2005 en adelante) - Clio 2 1.5 dCi K9K (2005 en adelante)	11 75 096 54R 8200360524 8200460446 8200608550 8200612619 8200861569 VKM 36055	
C3005 Unidireccionales	Peugeot 207 RC, CC, GTI 1.6 T / DS3 1.6 T / BMW : Mini Cooper, - Clubman, -S, SClubman, JCW, - Clubman, One 1	INA : F-560565 Bosch : F00M391140 F00M349870	
G5/2-047 Poly-V	VW Amarok / Tiguan 2.0 Tdi, BiTdi - Fox / Suran 1.9 SDI - 1.9 TDI	038 903 315AD 038 903 315AG 038 903 315AH 038 903 315T VKM 31058	

NUEVOS PRODUCTOS 2012



Código	Aplicación	Nº Referencia	Foto
G5/2-048	Poly-V VW Amarok 2.0 Tdi, BiTdi	03G 145 276 VKM 31008	
C5006	Unidireccionales VW Amarok 2.0 Tdi, BiTdi	03G 903 119B 045 903 119A 045 903 119 F-551406 F-551406.01 551406.02 551406.03	